

### STATE OF TEXAS WELL REPORT for Tracking #158418

Owner:	Phillip Allen	Owner Well #:	No Data
Address:	1004 Leslie Ct. Arlington , TX 76012	Grid #:	41-39-5
Well Location:	CR 2998 Evant , TX 76525	Latitude:	31° 26' 25" N
Well County:	Lampasas	Longitude:	098° 11' 43" W
Elevation:	No Data	GPS Brand Used:	Map
<hr/>			
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Date:       Started: **9/13/2005**  
                           Completed: **9/14/2005**

Diameter of Hole:   Diameter: **9 in From Surface To 20 ft**  
                           Diameter: **6 in From 20 ft To 432 ft**

Drilling Method:    **Air Rotary**

Borehole  
Completion:         **Straight Wall**

Annular Seal Data:  **1st Interval: From 0 ft to 20 ft with 4 Cement (#sacks and material)**  
                           **2nd Interval: No Data**  
                           **3rd Interval: No Data**  
                           Method Used: **Gravity Feed**  
                           Cemented By: **No Data**  
                           Distance to Septic Field or other Concentrated Contamination: **None on site ft**  
                           Distance to Property Line: **50+ ft**  
                           Method of Verification: **Visual**  
                           Approved by Variance: **No Data**

Surface  
Completion:         **Surface Sleeve Installed**

Water Level:        Static level: **270 ft. below land surface on 9/14/2005**  
                           Artesian flow: **No Data**

Packers:            **Rubber 300'**

Plugging Info:     Casing or Cement/Bentonite left in well: **No Data**

Type Of Pump:      **No Data**

Well Tests:         **Jetted**  
                           Yield: **20 GPM with (No Data) ft drawdown after (No Data) hours**

Water Quality:     Type of Water: **Good**  
                           Depth of Strata: **No Data**  
                           Chemical Analysis Made: **No**  
                           Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for completion and resubmittal.

Company Information: **Harrison & Sons Well Service, Inc.**  
**P.O. Box 986**  
**Lampasas , TX 76550**

Driller License Number: **54176**

Licensed Well Driller Signature: **Juan Munoz**

Registered Driller Apprentice Signature: **No Data**

Apprentice Registration Number: **No Data**

Comments: **\$mew**

---

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #158418) on your written request.

**Texas Department of Licensing & Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 463-7880**

**DESC. & COLOR OF FORMATION MATERIAL**

From (ft) To (ft) Description  
**0 - 10 Overburden**  
**10 - 28 Gray Shale**  
**28 - 36 Fine Tan Sand**  
**36 - 60 Gummy / Sandy Shale**  
**60 - 292 Gray Shale**  
**292 - 328 Brown Limestone**  
**328 - 372 Broken Limestone (Water)**  
**372 - 400 Red Clay**  
**400 - 412 Limestone**  
**412 - 432 Red Clay**

**CASING, BLANK PIPE & WELL SCREEN DATA**

Dia.	New/Used	Type	Setting From/To
6	New	SCH 40 PVC	0 - 20
4 1/2	New	SDR 17 PVC	2 - 432
		Perforated	320 - 380