STATE OF TEXAS WELL REPORT for Tracking #253606				
Owner:	Ronny Muse	Owner Well #:	No Data	
Address:	502 Frank St Lampasas, TX 76550	Grid #:	41-32-5	
Well Location:	• •	Latitude:	31° 34' 12" N	
	Purmela, TX 76566	Longitude:	098° 04' 03" W	
Well County:	Hamilton	Elevation:	No Data	
Type of Work:	New Well	Proposed Use:	Domestic	

Drilling Start Date: 2/14/2006 Drilling End Date: 2/14/2006

	Diameter (in.) Top Dept	h (ft.)	Bottom Depth (ft.)		
Borehole:	9	0		22		
	6	22		460		
Drilling Method:	Air Rotary					
Borehole Completion:	Straight Wall					
	Top Depth (ft.)	Bottom Depth (ft.)	Des	cription (number of sacks & material)		
Annular Seal Data:	0	22		4 cement		
Seal Method: Gravity Feed Distance to Property Line (ft.): 50+						
Sealed By: Unknown		Distance to Septic Field or other concentrated contamination (ft.): 100+				
	Distance to Septic Tank (ft.): No Data					
			Method	of Verification: visual		
Surface Completion: Surface Sleeve Installed						
Water Level:	335 ft. below land surface on 2006-02-14 Measurement Method: Unknown					
Packers:	Rubber 380'					
Type of Pump:	No Data					
Well Tests:	Jetted	Yield: 20 GPM				

	Strata Depth (ft.)	Water Type		
Water Quality:	400	Good		
		Chemical Analysis Made	: No	
	Did the driller	knowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct supervi correct. The driller u	at the driller drilled this well (or the weision) and that each and all of the stat nderstood that failure to complete the sturned for completion and resubmitta	ements he required i	erein are true and
Certification Data: Company Information:	driller's direct supervi correct. The driller un the report(s) being re	ision) and that each and all of the stat nderstood that failure to complete the sturned for completion and resubmitta	ements he required i	erein are true and
	driller's direct supervi correct. The driller un the report(s) being re	ision) and that each and all of the stat nderstood that failure to complete the sturned for completion and resubmitta Nell Service, Inc.	ements he required i	erein are true and
	driller's direct supervi correct. The driller un the report(s) being re Harrison & Sons V P.O. Box 986	ision) and that each and all of the stat nderstood that failure to complete the sturned for completion and resubmitta Vell Service, Inc. 550	ements he required i	erein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	18	Overburden
18	35	Hard Limestone
35	55	Gummy Clay
55	282	Gray Shale
282	375	Fine Sandy Shale
375	378	Brown Limestone / Purple Clay
378	400	Brown Limestone
400	412	Fractures (Water)
412	424	Red Sandy Clay
424	460	Limestone

Casing: BLANK PIPE & WELL SCREEN DATA

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)		
6 New	6 New Sdr 21 PVC 0 - 22				
4-1/2 New Sdr 17 PVC 0 - 460					
4-1/2 New Perforated 400 - 460					

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540