# STATE OF TEXAS WELL REPORT for Tracking #100744

Owner: Mike Sota Owner Well #: No Data

Address: 2501 Bacon Ranch Road Grid #: 41-39-9

Kileen, TX 76541

Well Location: CR 3940

Evant, TX 76525

Latitude:

31° 24' 12" N

Longitude:

098° 09' 16" W

535

Well County: Lampasas Elevation: No Data

Type of Work: New Well Proposed Use: Domestic

Drilling Start Date: 9/20/2003 Drilling End Date: 9/20/2003

6

Borehole:

Diameter (in.)
Top Depth (ft.)
Bottom Depth (ft.)

0
30

Drilling Method: Air Rotary

Borehole Completion: Straight Wall

Annular Seal Data:

Top Depth (ft.)

Bottom Depth (ft.)

Description (number of sacks & material)

5

30

Seal Method: **Gravity Feed**Distance to Property Line (ft.): **No Data** 

Sealed By: **Driller** Distance to Septic Field or other

concentrated contamination (ft.): No Data

Distance to Septic Tank (ft.): No Data

Method of Verification: None on Site

Surface Completion: Surface Sleeve Installed

Water Level: No Data

Packers: Rubber 100

Rubber 460

Type of Pump: Submersible Pump Depth (ft.): 480

Well Tests: Estimated Yield: 16 GPM

Water Quality:

Strata Depth (ft.)	Water Type
No Data	Good

Chemical Analysis Made: No

Did the driller knowingly penetrate any strata which

contained injurious constituents?: No

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the

driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in

the report(s) being returned for completion and resubmittal.

Company Information: **Harrison Drilling** 

P. O. Box 986

Lampasas, TX 76550

Driller Name: **David Harrison** License Number: 1898

Comments: \$dfs

## Lithology: **DESCRIPTION & COLOR OF FORMATION MATERIAL**

#### Top (ft.) Bottom (ft.) Description 0 22 Overburden 22 75 **Gray Limestone** 75 87 Fine Tan Sand 87 377 **Gray Limestone** 404 377 **Tan Limestone Broken Brown Limestone** 404 420 420 447 Clay 447 503 **Hard Tan Limestone** 503 515 **Broken Limestone/Water** 515 535 Tan Limestone To Clay

# Casing: BLANK PIPE & WELL SCREEN DATA

Dia. (in.)	New/Used	Туре	Setting From/To (ft.)		
6 New Sch40 PVC 0 30					
4.5 New SDR17 PVC 0 535					
Perforated 475 535					

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540