STATE OF TEXAS WELL REPORT for Tracking #100799				
Owner:	Mike Sota	Owner Well #:	No Data	
Address:	2501 Bacon Ranch Road Killeen, TX  76541	Grid #:	41-39-9	
Well Location:	CR 3940	Latitude:	31° 24' 18" N	
	Evant, TX 76525	Longitude:	098° 09' 02" W	
Well County:	Lampasas	Elevation:	No Data	
Type of Work:	New Well	Proposed Use:	Domestic	

Drilling Start Date: 9/21/2003 Drilling End Date: 9/21/2003

	Diameter (in.,	) Top De	epth (ft.)	Bottom Depth (ft.)	
Borehole:	9	0		20	
	6	2	0	460	
Drilling Method:	Air Rotary				
Borehole Completion:	Straight Wall				
	Top Depth (ft.)	Bottom Depth (ft.)	De	scription (number of sacks & material)	
Annular Seal Data:	0	20		4	
Seal Method: Gr	avity Feed	Di	stance to P	operty Line (ft.): No Data	
Sealed By: Dr	iller			ic Field or other ntamination (ft.): <b>No Data</b>	
		[	Distance to	Septic Tank (ft.): <b>No Data</b>	
			Metho	d of Verification: None on Site	
Surface Completion:	Surface Sleeve Ir	nstalled			
Water Level:	No Data				
Packers:	Rubber 40' Rubber 360'				
Type of Pump:	Submersible		Pu	mp Depth (ft.): <b>400</b>	
Well Tests:	Estimated	Yield: 10 GPM			

	Strata Depth (ft.)	Water Type	-	
Water Quality:	No Data	Good		
		Chemical Analysis Made	: No	
	Did the driller	knowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct superv correct. The driller u	nat the driller drilled this well (or the we ision) and that each and all of the stat inderstood that failure to complete the eturned for completion and resubmitta	ements he required it	erein are true and
Certification Data: Company Information:	driller's direct superv correct. The driller u the report(s) being re	ision) and that each and all of the stat inderstood that failure to complete the	ements he required it	erein are true and
	driller's direct superv correct. The driller u the report(s) being re	rision) and that each and all of the stat inderstood that failure to complete the eturned for completion and resubmitta	ements he required it	erein are true and
	driller's direct superv correct. The driller u the report(s) being re Harrison Drilling P. O. Box 986	rision) and that each and all of the stat inderstood that failure to complete the eturned for completion and resubmitta 550	ements he required it	erein are true and

Casing: BLANK PIPE & WELL SCREEN DATA

## Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description	Dia. (in.) New/Used Type Setting From/To (ft.)
0	20	Overburden	6 New Sch40 PVC 0 20
20	76	Gray Limestone	4.5 New SDR 17 PVC 0 460
76	96	Fine Tan Sand	Perforated 400 460
96	380	Gray Limestone	
380	399	Tan Limestone	
399	445	Broken Limestone/Water	
445	460	Red Clay	

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540